FORM MR-AR (Revised 2/2001)

## STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801

Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940

## ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	<u>Gene</u>	General Information			
	1.	Report Time Period: From (mo./yr.) 01/04 To (mo./yr.) 12/04			
	2.	DOGM File Number (Mine No): M / 01/027			
	3.	Mine Name: Pearl Queen Mine			
	4.	Mineral(s) Mined (or permitted to mine): Perlite			
	<b>5</b> .	Type of mine Surface Mine or Underground Mine			
	6.	Legal Description (Location of Lands Affected):			
		1/4,1/4,1/4. Section1 . Township275, Range _9W			
		1/4,1/4,1/4. Section2 . Township275_ Range9W			
		1/4,1/4,1/4, Section, Township, Range			
7.	Nam	Name of Operator or Company: Rasin Perlite Company			
	8. Permanent Street Address: P.O. Box 490, 533 S Industrial loop				
		City, State, Zip: Milford, UT 84751			
		Phone: (435) 387-2100 Fax: (435) 387-2403			
	9.	Company Representative (or designated operator):			
		Name: Timothy L. Hall			
		Title: President			
		Business Address: P.O. Box 490			
		City, State, Zip: Milford, UT 84751			
		Phone: (435) 387-2100 Fax: (435) 387-2403			
		Please check if any of the above information has changed since previous year.			
П.	<u>Mini</u>	ng and Reclamation			
	1.	Was there any mine related activity during the past year? Yes 🖫 No 🗆			
	2.	If no - what was the last year of activity?			
	3.	If yes - how much one or mineral was mined? 34,205 Short Tons			
		RECEIVED			

MAR 2 2 2005

DIV. OF OIL, GAS & MINING

1 M 3/11/05

4,	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.			
		hauled from Schoo Pit.		
		and processed product.		
5.	How much additional acreage was di	sturbed during the past year? 1.3 Acres		
6.		ring the past year? 7 Acres		
7.	Briefly describe the reclamation work should include methods employed, and	performed during the past year. This description		
	•			
8.	What is the total disturbed acreage of entire project at years end? 22 Acres			
9.	Briefly summarize any mining and/or reclamation plans for the upcoming year.			
	Contine to mine in the Schoo Pit.			
	Finish reclamation at the Pearl Queen Pit			
	·			
NOTE;	Section III., "Additional Information" applies only to large mining operations.			
III. <u>Additiona</u>	l Information - R647-4-121.2 and .3			
1.	The operator shall include an updated map depicting surface disturbance and reclamat performed during the year, prepared in accordance with Rule R647-4-105.			
2.	The operator shall keep and maintain time and shall make these records available to	nely records relating to his performance under the A the Division upon request.		
IV. Signatur	e Requirement			
I her	eby certify that the foregoing is tru	e and correct		
	Name (Typed or Print):	Timothy   . Hall		
	Title of Operator:	President		
	Signature of Operator:	L=27100		
	Date:	March 22, 2005		

jb o:\forme\reports\MR-AR



